


Donning PPE for droplet precautions

- Don the PPE step-by-step in the depicted sequence
- Perform donning in a clean area
- It is advised to be observed by a trained colleague during donning

Revised: 11.04.2020

1



Remove all hard or bulky objects from your person. Only wear light work clothing and shoes. Wash or disinfect your hands.

2



Fold out your surgical mask or respirator. Pull the elastic or fixate the band behind your head. Form the nose-piece firmly around your nose using both index fingers.

3




Use goggles or other tight-fitting protective eyewear. Visor can be used instead, but shall not be donned until step 4 (so that the visor sits outside the hood).

4




Use a surgical head cover, bouffant cap or astronaut hood. Pack hair well inside the head cover. Visor can be used instead of or in addition to other protective eyewear.

5



Put the gown with the opening in the back. Close in the back of your neck. Pull the strings around your waist and tie a knot in the front.

6



Put on gloves. Pull them up and beyond the cuffs of the gown. The gloves can be changed between procedures or when they get dirty.